

h0@

) - U


-V

#- U

h0h  
-V "




) - t  
#- h

" f y  
E " X phh




h0V

) - 7 U






Nr	Xmm	Ymm	Zmm	Szt.
1	1800	400	16	1
2	1800	380	16	1
3	317	380	16	1
4	317	380	16	1
5	869	348	16	1
6	433	328	16	1
7	70	921	16	1
8	433	328	16	1
9	921	129	16	1
10	317	380	16	1
11	317	380	16	1
12	417	317	16	2
13	901	183	16	1
14	869	70	16	1
15	901	400	16	1




<b>A1</b> 18 x Ø7x50 	<b>I12</b> 24 x Ø4/Ø10 	<b>B1</b> 42 x Ø8x35 	<b>K5</b> 17 x 34mm 	<b>K1</b> 17 x Ø15x12 	<b>I20</b> 9 x Ø4/Ø17 
<b>D4</b> 2 x 	<b>C4</b> 2 x 	<b>G34</b> 28 x 3,5x16 	<b>C3</b> 4 x KLIK 	<b>D3</b> 4 x KLIK 	<b>G20</b> 4 x Ø5x13 
<b>H24</b> 1 x 350/90 	<b>L9</b> 2 x 	<b>G3</b> 12 x 4x30 	<b>P11</b> 6 x 60x60 	<b>W2</b> 1 x 4mm 	<b>U8</b> 6 x Ø10x50 
<b>A2</b> 6 x Ø7x70 					





I




II




III




IV



V



VI a



VI b

