






MEUBLES
DEMEYERE

SAV
SPAREPARTS
KUNDERDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

416170_0

147975_0

58731



(FR) SECURITE
IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

(GB) CAUTION
IMPORTANT-TO BE READED CAREFULLY-TO BE
CONSERVED FOR LATER CONSULTATION

(DE) SICHERHEITSVORSCHRIFTEN
WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH


(ES) SEGURIDAD
IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

(NL) VEILIGHEID
BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING


(IT) SICUREZZA
IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE















(PT) SEGURANCA
IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR

(PL) UWAGA
WAZNE-UWAZNIE PRZECZYTAC-ZACHOWAC
CELEM POZNIEJSZYCH KONSULTACJI





REP	DIM	QTE
1	1823x550	2
2	899x549	2
3	899x513	1
4	899x513	1
5	1826x503	1
6	1815x928	1
7	1826x503	1



560	X6	333009	X8	333012	X8	604757	X30	729	X4
									Ø8
39858	X1	935	X2	949	X16	310040	x2	351524	X4
 L=892mm		 3*12		 3.5*15					
354000	X12	71	X12		X2				
				 +  4x30					

1

354000	X8	333012	X8	949	X16	351524	X4	560	X6



2

71


X8

729

X4




Ø8



3

71



X4



4

333009



X4




5

333009

X4






6








7

604757 X30




8

310040	x2	39858	X1	935	X2
					



9

	X2
	+ 