







MEUBLES  
DEMEYERE

SAV  
SPAREPARTS  
KUNDEDIENST  
POST VENTAS  
SERVICE NA VERKOOP  
SERVIZIO POST-VENDITA  
SERVICO DEPOIS DE VENDA  
SERWIS POGWARANCYJNY

467464  
468464



Rep	Dim.	Qté
1	1560x362	1
2	1560x362	1
3	504x363	1
4	470x361	2
5	470x360	2



1H 00 MN



(FR)

### SECURITE

IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER  
POUR CONSULTATION ULTERIEURE

(GB)

### CAUTION

IMPORTANT-TO BE READED CAREFULLY-TO BE  
CONSERVED FOR LATER CONSULTATION

(DE)

### SICHERHEITSVORSCHRIFTEN

WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN  
FÜR SPÄTEREN GEBRAUCH

(ES)

### SEGURIDAD

IMPORTANTE-LEER CON ATENCION-CONSERVAR  
PARA CONSULTAS POSTERIORES

(NL)

### VEILIGHEID

BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD  
TE WORDEN VOOR LATERE RAADPLEGING

(IT)

### SICUREZZA

IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA  
CONSERVARE PER CONSULTAZIONE ULTERIORE

(PT)





### SEGURANCA

IMPORTANTE-PARA LER COM ATENCAO-PARA  
CONSERVAR PARA COOSULTA ULTERIOR


(PL)

### UWAGA

WAZNE-UWAZNIE PRZECZYTAC-ZACHOWAC  
CELEM POZNIEJSZYCH KONSULTACJI




706	X8	70	X12	71	X12	331144	X1	729	X8	604757	X1
											x30
1	70	X12	729	X8							




2

71 X8



3

71 X4







# 4

331144

X1

604757


X1




# 5

706


X8



1°



2°



3°

