





MEUBLES
DEMEYERE



SAV
SPAREPARTS
KUNDEDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

58589

468463



Rep	Dim.	Qté
1	730x499	1
2	730x499	1
3	1326x500	1
4	468x498	1
5	730x499	1
6	809x244	1
7	464x187	2
8	468x91	1
9	1220x160	2
10	446x380	2
11	497x323	1



1 H 30 MN



FR SECURITE
IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

GB CAUTION
IMPORTANT-TO BE READED CAREFULLY-TO BE
CONSERVED FOR LATER CONSULTATION

DE SICHERHEITSVORSCHRIFTEN
WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH




ES SEGURIDAD
IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

NL VEILIGHEID
BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING

IT SICUREZZA
IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE

PT SEGURANCA
IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR

PL UWAGA
WAZNE-UWAZNIE PRZECZYTAĆ-ZACHOWAĆ
CELEM POZNIJESZYCH KONSULTACJI



FABRICATION FRANCAISE


70	X16	71	X16	1625	X4	160	X4	90	X8	729	X10

510	X2	340286	X2	604757	X1	332254	X2	913	X4	732	X1


495	X2	928	X8	983	X4	340930	X2	1107	X6	331144	X1

1	332254	X2	913	X4	732	X1

x2




2	495	X2	928	X8	70	X6



3

729




X6



4

71




X6



5A

70




X6



5B



70

X6






6A

729	X4	70	X2
-----	----	----	----






6B

729	X4	70	X2	510	X2
-----	----	----	----	-----	----



7

71	X2
----	----







8A

70

X2

71

X2









8B

71

X4

1107

X4








9A

71

X6






1107

X6








9B

71	X2	1107	X2	340286	X2	340930	X2
----	----	------	----	--------	----	--------	----







10A

331144	X1	604757	X1
--------	----	--------	----



10B

331144	X1	604757	X1
--------	----	--------	----





11A

983 X4



4x9





11B




983 X4






4x9



12A

1625	X4	160	X4	90	X8
					



12B

1625	X4	160	X4	90	X4
